

**RoHS MIGRATION FAX PRODUCTS:**

| Non RoHS Part Number                  | Non RoHS Model                           | RoHS Part Number | RoHS Model                                 | Software Required for RoHS cards | Date that Non RoHS product EOL          |
|---------------------------------------|--|------------------|--|----------------------------------|---|
| <b>TR1034 Series</b>                  |  |                  |  |                                  |   |
| 904-034-80                            | TR1034+P2-2L                             | 901-002-06       | TR1034+P2-2L-R                             | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-034-82                            | TR1034+P2-2L ZA/NZ/HK/SG                 | 901-002-08       | TR1034+P2-2L-R ZA/NZ/HK/SG                 | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-00                            | TR1034+P4-4L                             | 901-002-09       | TR1034+P4-4L-R                             | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-02                            | TR1034+P4-4L ZA/NZ/HK/SG                 | 901-002-11       | TR1034+P4-4L-R ZA/NZ/HK/SG                 | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-20                            | TR1034+P8-8L                             | 901-002-12       | TR1034+P8-8L-R                             | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-22                            | TR1034+P8-8L ZA/NZ/HK                    | 901-002-13       | TR1034+P8-8L-R ZA/NZ/HK                    | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-034-81                            | TR1034+P2-2L UK                          | 901-002-07       | TR1034+P2-2L-R UK                          | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-01                            | TR1034+P4-4L UK                          | 901-002-10       | TR1034+P4-4L-R UK                          | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-21                            | TR1034+P8-8L UK                          | 901-002-14       | TR1034+P8-8L-R UK                          | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-034-70                            | TR1034+P2-1B                             | 901-003-03       | TR1034+P2-1B-R                             | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-034-71                            | TR1034+P2-1B ZA/NZ                       | 901-003-04       | TR1034+P2-1B-R ZA/NZ                       | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-034-90                            | TR1034+P4-2B                             | 901-003-05       | TR1034+P4-2B-R                             | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-034-91                            | TR1034+P4-2B ZA/NZ                       | 901-003-06       | TR1034+P4-2B-R ZA/NZ                       | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 900-190-12                            | TR1034+P4H-T1-1N                         | 901-001-14       | TR1034+P4H-T1-1N-R                         | SDK 3.3 or greater               | Non-RoHS discontinued August 15, 2006   |
| 900-190-21                            | TR1034+P8H-T1-1N                         | 901-001-16       | TR1034+P8H-T1-1N-R                         | SDK 3.3 or greater               | Non-RoHS discontinued August 15, 2006   |
| 900-190-31                            | TR1034+P16H-T1-1N                        | 901-001-09       | TR1034+P16H-T1-1N-R                        | SDK 3.3 or greater               | Non-RoHS discontinued August 15, 2006   |
| 900-190-41                            | TR1034+P24H-T1-1N                        | 901-001-11       | TR1034+P24H-T1-1N-R                        | SDK 3.3 or greater               | Non-RoHS discontinued August 15, 2006   |
| 900-190-13                            | TR1034+P4H-E1-1N                         | 901-001-13       | TR1034+P4H-E1-1N-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 900-190-51                            | TR1034+P8H-E1-1N                         | 901-001-15       | TR1034+P8H-E1-1N-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 900-190-61                            | TR1034+P10H-E1-1N                        | 901-001-07       | TR1034+P10H-E1-1N-R                        | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 900-190-71                            | TR1034+P16H-E1-1N                        | 901-001-08       | TR1034+P16H-E1-1N-R                        | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 900-190-91                            | TR1034+P20H-E1-1N                        | 901-001-10       | TR1034+P20H-E1-1N-R                        | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 900-190-81                            | TR1034+P30H-E1-1N                        | 901-001-12       | TR1034+P30H-E1-1N-R                        | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| <b>TR114 US / Canada - DID Boards</b> |  |                  |  |                                  |   |
| 904-032-20                            | TR114+uP2C                               | 901-004-01       | TR1034+UP2C-R                              | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-032-10                            | TR114+uP2D                               | 901-004-02       | TR1034+uP2D-R                              | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-033-40                            | TR114+uP4C                               | 901-004-03       | TR1034+uP4C-R                              | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-032-70                            | TR114+uP4D                               | 901-004-04       | TR1034+uP4D-R                              | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| <b>TruFax Series</b>                  |  |                  |  |                                  |   |
| 904-030-50                            | TruFax 200 Universal PCI                 | 901-004-08       | Trufax 200-R PCI                           | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-030-40                            | TruFax 100 Universal PCI                 | 901-004-07       | Trufax 100-R PCI                           | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-030-81                            | TruFax 200 Universal PCI SA              | 901-004-08       | Trufax 200-R PCI                           | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-030-71                            | TruFax 100 Universal PCI SA              | 901-004-07       | Trufax 100-R PCI                           | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-030-80                            | TruFax 200 Universal PCI International   | 901-002-16       | TruFax Full Size 200-R Europe              | SDK 3.3 or greater               | Non-RoHS discontinued December 30, 2006 |
|                                       |  | 901-002-18       | Trufax Full Size 200- UK                   | SDK 3.3 or greater               | Non-RoHS discontinued December 30, 2006 |
|                                       |  | 901-004-08       | Trufax 200-R PCI                           | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
|                                       |  | 901-004-10       | TruFax 200-R PCI UK                        | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-030-70                            | TruFax 100 Universal PCI International   | 901-002-15       | TruFax Full Size 100-R Europe              | SDK 3.3 or greater               | Non-RoHS discontinued December 30, 2006 |
|                                       |  | 901-002-17       | Trufax Full Size 100- UK                   | SDK 3.3 or greater               | Non-RoHS discontinued December 30, 2006 |
|                                       |  | 901-004-07       | Trufax 100-R PCI                           | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
|                                       |  | 901-004-09       | TruFax 100-R PCI UK                        | SDK 5.0 or greater               | Non-RoHS discontinued December 30, 2006 |
| 904-035-30                            | TruFax 200 BRI (2B+D)                    | 901-003-07       | TruFax 200-R BRI (2B+D)                    | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-31                            | TruFax 250 BRI (2B+D)                    | 901-003-08       | TruFax 250-R BRI (2B+D)                    | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-40                            | TruFax 400 BRI (4B+2D)                   | 901-003-09       | TruFax 400-R BRI (4B+2D)                   | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 904-035-41                            | TruFax 450 BRI (4B+2D)                   | 901-003-10       | TruFax 450-R BRI (4B+2D)                   | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006      |
| 994-113-50                            | TruFax 200 Microsoft Shared Fax          | 999-169-13       | TruFax 200 -R PCI for Microsoft Shared Fax | Ships with product               | Non-RoHS discontinued December 30, 2006 |
| 994-113-70                            | TruFax 100 for Microsoft Shared Fax      | 999-169-12       | TruFax 100 -R PCI for Microsoft Shared Fax | Ships with product               | Non-RoHS discontinued December 30, 2006 |
| 994-113-60                            | TruFax 200 Intl for Microsoft Shared Fax | 999-169-13       | TruFax 200 -R PCI for Microsoft Shared Fax | Ships with product               | Non-RoHS discontinued December 30, 2006 |
| 994-113-80                            | TruFax 100 Intl for Microsoft Shared Fax | 999-169-12       | TruFax 100 -R PCI for Microsoft Shared Fax | Ships with product               | Non-RoHS discontinued December 30, 2006 |

**RoHS MIGRATION TR1000 VOICE PRODUCTS:**

| Non RoHS Part Number                  | Non RoHS Model      | RoHS Part Number | RoHS Model                                | Software Required for RoHS cards | Date that Non RoHS product will EOL   |
|---------------------------------------|---------------------|------------------|---|----------------------------------|---------------------------------------|
| <b>TR1000 Microsoft Speech Server</b> |                     |                  |   |                                  |                                       |
| 904-193-01                            | TR1000+P4V-4L-SK    | 901-002-02       | TR1000+P4V-4L-R-SK-R                      | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-193-02                            | TR1000+P4v-4L-S     | 901-002-03       | TR1000+P4v-4L-S-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-193-03                            | TR1000+P8v-8L-S     | 901-002-05       | TR1000+P8v-8L-S-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-193-04                            | TR1000+P24vH-T1-S   | 901-001-02       | TR1000+P24vH-T1-S-R                       | SDK 3.3 or greater               | Non-RoHS discontinued August 15, 2006 |
| 904-193-05                            | TR1000+P48vH-2T1-S  | 901-001-05       | TR1000+P48vH-2T1-S-R                      | SDK 4.1 or greater               | Non-RoHS discontinued July 1, 2006    |
|                                       | new!                | 901-003-13       | TR1000+P2v-1B-SK-R                        | SDK 5.0 or greater               | n/a                                   |
|                                       | new!                | 901-003-11       | TR1000+P2v-1B-S-R                         | SDK 5.0 or greater               | n/a                                   |
|                                       | new!                | 901-003-12       | TR1000+P4v-2B-S-R                         | SDK 5.0 or greater               | n/a                                   |
|                                       | new!                | 901-001-17       | TR1000+P30vH-E1-S-R                       | SDK 5.0 or greater               | n/a                                   |
|                                       | new!                | 901-000-39       | TR1000+P60V-2E1-S-R                       | SDK 5.0 or greater               | n/a                                   |
|                                       | new!                | 901-000-40       | TR1000+120V-4E1-S-R                       | SDK 5.0 or greater               | n/a                                   |
|                                       | new!                | 901-000-37       | TR1000+96V-4T1-S-R                        | SDK 5.0 or greater               | n/a                                   |
| <b>TR1000 Series Analog</b>           |                     |                  |   |                                  |                                       |
| 904-035-90                            | TR1000+P4v1f-4L     | 901-002-01       | TR1000+P4v1f-4L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-035-94                            | TR1000+P4v1fH-4L    | n/a              | no RoHS replacement- recommend 901-002-01 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-036-10                            | TR1000+P8v2f-8L     | 901-002-04       | TR1000+P8v2f-8L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-036-13                            | TR1000+P8v2fH-8L    | n/a              | no RoHS replacement- recommend 901-002-04 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-036-00                            | TR1000+P4v-4L       | 901-002-01       | TR1000+P4v1f-4L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-036-02                            | TR1000+P4vH-4L      | n/a              | no RoHS replacement- recommend 901-002-01 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-036-20                            | TR1000+P8v-8L       | 901-002-04       | TR1000+P8v2f-8L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-036-22                            | TR1000+P8vH8L       | n/a              | no RoHS replacement- recommend 901-002-04 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-036-01                            | TR1000-P4V-4L UK    | 901-002-01       | TR1000+P4v1f-4L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-035-93                            | TR1000-P4V1F-4L UK  | 901-002-01       | TR1000+P4v1f-4L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-036-21                            | TR1000-P8V-8L UK    | 901-002-04       | TR1000+P8v2f-8L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-036-12                            | TR1000-P8V2F-8L UK  | 901-002-04       | TR1000+P8v2f-8L-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-036-03                            | TR1000-P4VH-4L UK   | n/a              | no RoHS replacement- recommend 901-002-01 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-035-95                            | TR1000-P4V1FH-4L UK | n/a              | no RoHS replacement- recommend 901-002-01 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-036-23                            | TR1000-P8VH-8L UK   | n/a              | no RoHS replacement- recommend 901-002-04 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-036-14                            | TR1000-P8V2FH-8L UK | n/a              | no RoHS replacement- recommend 901-002-04 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| <b>TR1000 Series BRI</b>              |                     |                  |   |                                  |                                       |
| 904-035-60                            | TR1000+P2v1f-1B     | 901-003-01       | TR1000+P2v1f-1B-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-035-70                            | TR1000+P4v1f-2B     | 901-003-02       | TR1000+P4v1f-2B-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-035-71                            | TR1000+P4v1fH-2B    | n/a              | no RoHS replacement- recommend 901-003-02 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| 904-035-50                            | TR1000+P2v-1B       | 901-003-01       | TR1000+P2v1f-1B-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-035-80                            | TR1000+P4v-2B       | 901-003-02       | TR1000+P4v1f-2B-R                         | SDK 3.3 or greater               | Non-RoHS discontinued July 1, 2006    |
| 904-035-81                            | TR1000+P4vH-2B      | n/a              | no RoHS replacement- recommend 901-003-02 | n/a                              | Non-RoHS discontinued July 1, 2006    |
| <b>TR1000 Series T1/E1</b>            |                     |                  |   |                                  |                                       |

|                           |                                     |            |   |                    |                                       |
|---------------------------|-------------------------------------|------------|---|--------------------|---------------------------------------|
| 900-168-31                | TR1000+P24v8fH-T1                   | 901-001-01 | TR1000+P24v8fH-T1-R   | SDK 3.3 or greater | Non-RoHS discontinued August 15, 2006 |
| 900-168-32                | TR1000+P30v8fH-E1                   | 901-001-03 | TR1000+P30v8fH-E1-R   | SDK 3.3 or greater | Non-RoHS discontinued July 1, 2006    |
| 901-000-11                | TR1000+P48V8fH-2T1-R                | n/a        | no replacement required. The RoHS version of this product is shipping today.          | SDK 4.1 or greater | Non-RoHS discontinued August 15, 2006 |
| 901-000-12                | TR1000+P60V8fH-2E1-R                | n/a        | no replacement required. The RoHS version of this product is shipping today.          | SDK 4.1 or greater | Non-RoHS discontinued August 15, 2006 |
| 901-000-13                | TR1000+P96V16fH-4T1-R               | n/a        | no replacement required. The RoHS version of this product is shipping today.          | SDK 4.1 or greater | Non-RoHS discontinued August 15, 2006 |
| 901-000-14                | TR1000+120V16fH-4E1-R               | n/a        | no replacement required. The RoHS version of this product is shipping today.          | SDK 4.1 or greater | Non-RoHS discontinued August 15, 2006 |
| 900-168-22                | TR1000+P96vH-2T1                    | n/a        | No RoHS Replacement planned. Special arrangements may be made to sell this product to | SDK 4.1 or greater | Non-RoHS discontinued August 15, 2006 |
| 900-168-10                | TR1000+P24vH-T1                     | 901-001-01 | TR1000+P24v8fH-T1-R   | SDK 3.3 or greater | Non-RoHS discontinued August 15, 2006 |
| 900-168-12                | TR1000+P30vH-E1                     | 901-001-03 | TR1000+P30v8fH-E1-R   | SDK 3.3 or greater | Non-RoHS discontinued July 1, 2006    |
| 900-168-14                | TR1000+P48vH-2T1                    | 901-000-11 | TR1000+P48v8fH-2T1-R  | SDK 4.1 or greater | Non-RoHS discontinued July 1, 2006    |
| 900-168-16                | TR1000+P60vH-2E1                    | 901-000-12 | TR1000+P60v8fH-2E1-R  | SDK 4.1 or greater | Non-RoHS discontinued July 1, 2006    |
| 994-115-20                | TR1000+P96vH-4T1 Bundle             | 901-000-13 | TR1000+P96v16fH-4T1-R   | SDK 4.1 or greater | Non-RoHS discontinued July 1, 2006    |
| 994-115-30                | TR1000+P120vH-4E1 Bundle            | 901-000-14 | TR1000+P120v16fH-4E1-R  | SDK 4.1 or greater | Non-RoHS discontinued July 1, 2006    |
| <b>TR1000 Accessories</b> |                                     |            |   |                    |                                       |
| 350-280-17                | Bus-Adaptor-H100-to-SCbus           | n/a        | no RoHS replacement   | discontinued       | Non-RoHS discontinued July 1, 2006    |
| 340-146-81                | 75 Ohm BNC to 120 Ohm RJ-45 adaptor | n/a        | no RoHS replacement   | discontinued       | Non-RoHS discontinued July 1, 2006    |

**RoHS MIGRATION VOICE PRODUCTS:**

| Part Number  | Model (today)                  | Replacement Model   |
|--|--------------------------------|---------------------|
| <b>Brooktrout Vantage US - ISA (Voice Resource &amp; Interface)</b>            |                                |                     |
| 904-007-90   | VANTAGE VOLARE                 | No RoHS replacement |
| 904-011-90   | VANTAGE VOLARE W/OBR           | No RoHS replacement |
| <b>Brooktrout Vantage US - ISA (Voice Resource only)</b>                       |                                |                     |
| 904-005-10   | VANTAGE VRS-16                 | No RoHS replacement |
| 904-005-50   | VANTAGE VRS-16 W/OBR           | No RoHS replacement |
| 904-005-20   | VANTAGE VRS-24                 | No RoHS replacement |
| 904-005-60   | VANTAGE VRS-24 W/OBR           | No RoHS replacement |
| 904-010-70   | VANTAGE VRS-32                 | No RoHS replacement |
| 904-005-70   | VANTAGE VRS-32 W/OBR           | No RoHS replacement |
| <b>Brooktrout Vantage US - PCI (Voice Resource &amp; Interface)</b>            |                                |                     |
| 904-008-20   | VANTAGE PCI4L                  | No RoHS replacement |
| 904-008-30   | VANTAGE PCI4L W/OBR            | No RoHS replacement |
| 904-008-40   | VANTAGE PCI4LHX                | No RoHS replacement |
| 904-008-50   | VANTAGE PCI4LHX W/OBR          | No RoHS replacement |
| 904-008-60   | VANTAGE PCI8L                  | No RoHS replacement |
| 904-008-70   | VANTAGE PCI8L W/OBR            | No RoHS replacement |
| 904-008-80   | VANTAGE PCI8LHX                | No RoHS replacement |
| 904-008-90   | VANTAGE PCI8LHX W/OBR          | No RoHS replacement |
| <b>Brooktrout Vantage US - PCI (Voice Resource only)</b>                       |                                |                     |
| 904-019-00   | VRS-16-PCI                     | No RoHS replacement |
| 904-019-10   | VRS-16-PCI W/OBR               | No RoHS replacement |
| 904-019-20   | VRS-24-PCI                     | No RoHS replacement |
| 904-019-30   | VRS-24-PCI W/OBR               | No RoHS replacement |
| 904-019-40   | VRS-32-PCI                     | No RoHS replacement |
| 904-019-50   | VRS-32-PCI W/OBR               | No RoHS replacement |
| <b>Brooktrout Vantage International - ISA (Voice Resource &amp; Interface)</b> |                                |                     |
| 904-008-10   | VANTAGE VOLARE, EURO, 4PORT    | No RoHS replacement |
| 904-008-00   | VANTAGE VOLARE, EURO, 4P W/OBR | No RoHS replacement |
| <b>Brooktrout Vantage International - PCI (Voice Resource &amp; Interface)</b> |                                |                     |
| 904-012-30   | VANTAGE PCI4L-I                | No RoHS replacement |
| 904-012-40   | VANTAGE PCI4L-I W/OBR          | No RoHS replacement |
| 904-012-60   | VANTAGE PCI4LHX-I              | No RoHS replacement |
| 904-012-00   | VANTAGE PCI4LHX-I W/OBR        | No RoHS replacement |
| 904-012-50   | VANTAGE PCI8L-I                | No RoHS replacement |
| 904-013-00   | VANTAGE PCI8L-I W/OBR          | No RoHS replacement |
| 904-012-70   | VANTAGE PCI8LHX-I              | No RoHS replacement |
| 904-012-80   | VANTAGE PCI8LHX-I W/OBR        | No RoHS replacement |
| 904-017-30   | VANTAGE PCI4L (AU)             | No RoHS replacement |
| 904-017-40   | VANTAGE PCI4L (AU) W/OBR       | No RoHS replacement |
| 904-017-50   | VANTAGE PCI4LHX (AU)           | No RoHS replacement |
| 904-017-60   | VANTAGE PCI4LHX (AU) W/OBR     | No RoHS replacement |
| 904-017-10   | VANTAGE PCI8L (AU)             | No RoHS replacement |
| 904-017-20   | VANTAGE PCI8L (AU) W/OBR       | No RoHS replacement |
| 904-017-70   | VANTAGE PCI8LHX (AU)           | No RoHS replacement |
| 904-017-80   | VANTAGE PCI8LHX (AU) W/OBR     | No RoHS replacement |
| 904-015-40   | VANTAGE PCI4L HK               | No RoHS replacement |
| 904-015-50   | VANTAGE PCI4L HK W/OBR         | No RoHS replacement |
| 904-015-60   | VANTAGE PCI4LHX HK             | No RoHS replacement |
| 904-015-70   | VANTAGE PCI4LHX HK W/OBR       | No RoHS replacement |
| 904-015-20   | VANTAGE PCI8L HK               | No RoHS replacement |
| 904-015-30   | VANTAGE PCI8L HK W/OBR         | No RoHS replacement |
| 904-015-80   | VANTAGE PCI8LHX HK             | No RoHS replacement |
| 904-015-90   | VANTAGE PCI8LHX HK W/OBR       | No RoHS replacement |
| 904-014-60   | VANTAGE PCI4L (JP)             | No RoHS replacement |
| 904-014-70   | VANTAGE PCI4L (JP) W/OBR       | No RoHS replacement |
| 904-014-80   | VANTAGE PCI4LHX (JP)           | No RoHS replacement |
| 904-014-90   | VANTAGE PCI4LHX (JP) W/OBR     | No RoHS replacement |
| 904-014-40   | VANTAGE PCI8L (JP)             | No RoHS replacement |
| 904-014-50   | VANTAGE PCI8L (JP) W/OBR       | No RoHS replacement |
| 904-015-00   | VANTAGE PCI8LHX (JP)           | No RoHS replacement |
| 904-015-10   | VANTAGE PCI8LHX (JP) W/OBR     | No RoHS replacement |
| 904-002-00   | DUET                           | No RoHS replacement |
| 904-002-20   | QUARTET                        | No RoHS replacement |
| 904-002-10   | 232                            | No RoHS replacement |
| 904-002-40   | 432                            | No RoHS replacement |
| 904-009-50   | RDSP-16000                     | No RoHS replacement |
| 904-009-60   | RDSP-20000                     | No RoHS replacement |
| 904-009-70   | RDSP-24000                     | No RoHS replacement |
| 904-028-10   | RealBLOCs 8-ATI                | No RoHS replacement |
| 904-025-80   | RealBLOCs 16-ATI               | No RoHS replacement |
| 904-025-60   | RealBLOCs 24-ATI               | No RoHS replacement |
| 904-028-01   | RealBLOCs 4-ASI                | No RoHS replacement |
| 904-028-00   | RealBLOCs 8-ASI                | No RoHS replacement |
| 904-025-90   | RealBLOCs 16-ASI               | No RoHS replacement |
| 904-025-70   | RealBLOCs 24-ASI               | No RoHS replacement |
| 904-029-70   | RealBLOCs 4-ATI/4-ASI          | No RoHS replacement |
| 904-029-80   | RealBLOCs 4-ATI/8-ASI          | No RoHS replacement |
| 904-029-90   | RealBLOCs 8-ATI/4-ASI          | No RoHS replacement |
| 904-030-00   | RealBLOCs 8-ATI/8-ASI          | No RoHS replacement |
| 904-026-00   | RealBLOCs 8-ATI/16-ASI         | No RoHS replacement |
| 904-026-20   | RealBLOCs 12-ATI/12-ASI        | No RoHS replacement |
| 904-026-10   | RealBLOCs 16-ATI/8-ASI         | No RoHS replacement |
| 904-030-10   | RealBLOCs DR-08-A              | No RoHS replacement |
| 904-030-20   | RealBLOCs DR-16-A              | No RoHS replacement |
| 904-030-30   | RealBLOCs DR-24-A              | No RoHS replacement |
| 904-025-71   | RealBLOCs DR-S 24              | No RoHS replacement |

**RoHS MIGRATION NETACCESS PRODUCTS:**

| Part Number                                 | Model (today)          | Replacement Model   |
|---|------------------------|---------------------|
| <b>PRI-PCI MVIP MODELS</b>                  |                        |                     |
| 150-0541-001                                | PRI-PCI24V             | No RoHS replacement |
| 150-0560-001                                | PRI-PCI24VC            | No RoHS replacement |
| 150-0544-001                                | PRI-PCI48V             | No RoHS replacement |
| 150-0551-001                                | PRI-PCI48VC            | No RoHS replacement |
| 150-0546-001                                | PRI-PCI64V             | No RoHS replacement |
| <b>PRI-PCI MVIP MODELS with Cables</b>      |                        |                     |
| 150-0549-001                                | PRI-PCI24V-C           | No RoHS replacement |
| 150-0801-001                                | PRI-PCI32V-C           | No RoHS replacement |
| 150-0796-001                                | PRI-PCI48V-C           | No RoHS replacement |
| 150-0797-001                                | PRI-PCI48VC-C          | No RoHS replacement |
| 150-0798-001                                | PRI-PCI64V-C           | No RoHS replacement |
| <b>PRI-PCI DATA ONLY MODELS</b>             |                        |                     |
| 150-0505-001                                | PRI-PCI24D             | No RoHS replacement |
| 150-0506-001                                | PRI-PCI24DC            | No RoHS replacement |
| 150-0511-001                                | PRI-PCI32D             | No RoHS replacement |
| 150-0542-001                                | PRI-PCI48D             | No RoHS replacement |
| 150-0543-001                                | PRI-PCI48DC            | No RoHS replacement |
| 150-0545-001                                | PRI-PCI64D             | No RoHS replacement |
| <b>PRI-PCI DATA+MVIP MODELS</b>             |                        |                     |
| 150-0509-001                                | PRI-PCI24DV            | No RoHS replacement |
| 150-0550-001                                | PRI-PCI24DVC           | No RoHS replacement |
| 150-0541-001                                | PRI-PCI32DV            | No RoHS replacement |
| 150-0507-001                                | PRI-PCI48DV            | No RoHS replacement |
| 907-120-12                                  | PRI-PCI48DV-HighZ      | No RoHS replacement |
| 150-0508-001                                | PRI-PCI48DVC           | No RoHS replacement |
| 150-0512-001                                | PRI-PCI64DV            | No RoHS replacement |
| 907-120-14                                  | PRI-PCI64DV-HighZ      | No RoHS replacement |
| <b>PRI-PCI DATA+MVIP MODELS with Cables</b> |                        |                     |
| 150-0799-001                                | PRI-PCI24DV-C          | No RoHS replacement |
| 150-0800-001                                | PRI-PCI24DVC-C         | No RoHS replacement |
| 150-0801-001                                | PRI-PCI32DV-C          | No RoHS replacement |
| <b>NS301 ePCI</b>                           |                        |                     |
| 907-120-01                                  | NS301-eP32DH-4P-AB     | No RoHS replacement |
| 907-120-02                                  | NS301-eP32DH-8P-AB     | No RoHS replacement |
| 907-120-00                                  | NS301-eP32DH           | No RoHS replacement |
| 907-120-03                                  | NS301-eP256DH          | No RoHS replacement |
| 907-120-04                                  | NS301-eP256DH-4P-AB    | No RoHS replacement |
| 907-120-05                                  | NS301-eP256DH-8P-AB    | No RoHS replacement |
| 907-120-15                                  | NS301-eP256DH-8P-HighZ | No RoHS replacement |
| 907-120-07                                  | NS301-eP544DH          | No RoHS replacement |
| 907-120-06                                  | NS301-eP544DH-8P-AB    | No RoHS replacement |
| <b>Old ePCI Models</b>                      |                        |                     |
| 151-2010-4AB                                | NS300-eP32DH-4P-AB     | No RoHS replacement |
| 151-2010-8AB                                | NS300-eP32DH-8P-AB     | No RoHS replacement |
| 151-2020-4AB                                | NS300-eP256DH-4P-AB    | No RoHS replacement |
| 151-2020-8AB                                | NS300-eP256DH-8P-AB    | No RoHS replacement |
| 151-2030-8AB                                | NS300-eP544DH-8P-AB    | No RoHS replacement |
| 151-2040-4AB                                | NS300-eP64LH-4P-AB     | No RoHS replacement |
| 151-2040-8AB                                | NS300-eP64LH-8P-AB     | No RoHS replacement |
| 151-2010-001                                | NS300-eP32DH           | No RoHS replacement |
| 151-2020-001                                | NS300-eP256DH          | No RoHS replacement |
| 151-2030-001                                | NS300-eP544DH          | No RoHS replacement |
| 151-2040-001                                | NS300-eP64LH           | No RoHS replacement |
| <b>NS300 Transition Modules</b>             |                        |                     |
| 150-0747-001                                | NS300-TM-8P-AB         | No RoHS replacement |
| 151-2050-4AB                                | NS300-TM-4P-AB         | No RoHS replacement |
| <b>CPCI TMs</b>                             |                        |                     |
| 150-0747-001                                | CPCI-TM-8P-AB          | No RoHS replacement |
| 150-0748-001                                | CPCI-TM-4P-AB          | No RoHS replacement |

| <b>Cables and Connectors</b>   |                        |                                     |                                     |
|--|------------------------|-------------------------------------|-------------------------------------|
| Non-RoHS version   | RoHS compliant version |                                     |                                     |
| 340-036-02 Cable Split Y 6' TR114  | 341-002-01             | CBL SPLIT Y 6' TR114 PB FREE        | CBL SPLIT Y 6' TR114 PB FREE        |
| 340-038-00 Cable TR114 2CH UK  | 341-002-02             | CBL TR114 2CH UK PB FREE            | CBL TR114 2CH UK PB FREE            |
| 340-094-00 Cable P4L Split   | 341-002-04             | CBL P4L 4 SPLIT PB FREE             | CBL P4L 4 SPLIT PB FREE             |
| 340-144-01 Cable Split 6 Feet TR114 DID (included in P2D, 1D, 14C, 14D boards) | 341-002-06             | CBL SPLIT 6FT TR114 DID PB FREE     | CBL SPLIT 6FT TR114 DID PB FREE     |
| 340-148-70 Cable TR114+PAL UK 4 Split 6'                                       | 341-002-09             | CBL TR114+PAL UK 4 SPLIT 6' PB FREE | CBL TR114+PAL UK 4 SPLIT 6' PB FREE |
| New  | 341-002-10             | CBL RJ45 TO RJ11 6' LOOP            | CBL RJ45 TO RJ11 6' LOOP            |
| New  | 341-002-11             | CBL RJ45 TO RJ11 6' DID             | CBL RJ45 TO RJ11 6' DID             |
| 344-002-40 Cable, H.100, 2 position  | 341-003-01             | CABLE.H.100.2 POSITION PB FREE      | CABLE.H.100.2 POSITION PB FREE      |
| 344-002-41 Cable, H.100, 12 position   | 341-003-02             | CABLE.H.100, 12 POSITION PB FREE    | CABLE.H.100, 12 POSITION PB FREE    |
| 344-002-50 Cable, H.100, 3 position  | 341-003-03             | CABLE.H.100.3 POSITION PB FREE      | CABLE.H.100.3 POSITION PB FREE      |
| 344-002-60 Cable, H.100, 4 position  | 341-003-04             | CABLE.H.100.4 POSITION PB FREE      | CABLE.H.100.4 POSITION PB FREE      |
| 344-002-70 Cable, H.100, 5 position  | 341-003-05             | CABLE.H.100.5 POSITION PB FREE      | CABLE.H.100.5 POSITION PB FREE      |
| 344-002-80 Cable, H.100, 6 position  | 341-003-06             | CABLE.H.100.6 POSITION PB FREE      | CABLE.H.100.6 POSITION PB FREE      |
| 344-002-90 Cable, H.100, 7 position  | 341-003-07             | CABLE.H.100.7 POSITION PB FREE      | CABLE.H.100.7 POSITION PB FREE      |
| 344-003-20 Cable, H.100, 8 position  | 341-003-08             | CABLE.H.100.8 POSITION PB FREE      | CABLE.H.100.8 POSITION PB FREE      |
| 340-101-00 Cable, RJ45 Cat5 Shielded 7'  | 341-004-01             | CBL RJ45 CAT5 SHIELDED 7' PB FREE   | CBL RJ45 CAT5 SHIELDED 7' PB FREE   |